

KPWD/AEE/PANDAVAPURA/BSC NO:02


DATED:05.06.2025.

BUILDING SAFETY CERTIFICATE

This is to Certified that I have inspected the building of Vidya Prachara Sangha® at Krishnanagara, Pandavapura Town, Mandya District and found that the Building is RCC framed structure having Ground Floor, First Floor and Second floor. In Ground Floor running **Vijaya Higher Primary School(CBSE)**. The building is Constructed for education purpose with sufficient light and ventilation facility. The above mentioned School is complied with the provisions of Building safety requirements in accordance with National Building Code Rules and verified by the officer of this office on 04-06-2025 in the presence of the Principal, Vijaya First Grade College, Krishnanagara, Pandavapura Town, Mandya District. Detailed inspection and test for the above building is Conducted by the Build point Constructions and Technologies, Gangothri Layout, Mysuru, a NABL Accredited testing Lab and submitted the report on 15-03-2024. Considering the report and Visual observation during inspection it is certified that the Building is structurally stable, safe and fit for running the school with effect from 05.06.2025 for a period of five year in accordance with the rule and subject to compliance of the specific Conditions as appended.

1. Regular maintenance of building & Plumbing works have to be taken up throughout the year.
2. Any major damages if occur during passage of time then those must be brought under the notice of competent authority.

Issued on 05.06.2025 by Karnataka Public Works Derpartment, Government of Karnataka.


Assistant Executive Engineer
P.W.D. No.7 Sub Division
Pandavapura.